

09/468173

copis

Patent 7,058,965 B1

PATENT

IN UNITED STATES PATENT AND TRADEMARK OFFICE

Patent No.: 7,058,965 B1

Docket No: SEDN/246

Issue Date: June 6, 2006

Patentee: Donald F. Gordon et al.

Title

MULTIPLEXING STRUCTURES FOR DELIVERY OF INTERACTIVE

PROGRAM GUIDE

REQUEST FOR CERTIFICATE OF CORRECTION

Commissioner for Patents P.O. Box 1450 Alexandria, VA 22313-1450

It is requested that a Certificate of Correction be issued correcting printing errors appearing in the above-identified United States patent. Two copies of the text of the Certificate in the suggested form are enclosed.

Please charge the certificate of correction fee, if any, pursuant to 37 CFR 1.20(a), to counsel's Deposit Account No. 20-0782/SEDN/246.

Issuance of the Certificate of Correction would neither expand nor contract the scope of the claims as properly allowed, and re-examination is not required.

The Examiner is authorized to charge any additional fees or credit overpayment to Deposit Account No. 20-0782/SEDN/246.

Respectfully submitted,

Certificate

JUL 3 1 2006

DONALD F. GORDON ET AL.

of Correction

Eamon J. Wall, Attorney, Reg. #39,414

Patterson and Sheridan, LLP

595 Shrewsbury Avenue, Suite 100 Shrewsbury, New Jersey 07702

CERTIFICATE UNDER 37 CFR § 1.8:

The undersigned hereby certifies that this correspondence is being deposited with the United States Postal Service with sufficient postage as first class mail, in an envelope addressed to: Commissioner for Patents, P.O. Box 1450 Alexandria, VA 22313-1450, on this 24 day of July 2006

LAULA E.

Name

07/27/2006 MBIZUNES 00000066 200782 7058965

01 FC:1811

100.00 DA

MIG , when

UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

PATENT NO : 7,058,965 B1

Page 1 of 3

DATED

: June 6, 2006

INVENTOR(S) : Donald F. Gordon et al.

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

In the first page, item (75), Inventors, line 5, delete "Shores" and insert instead --City--.

In the drawings, sheet 12 of 48, FIG. 11, matrix entry 1130, below boxes containing "g1," "g2," "g3," and "g10" delete "COLUM" and insert instead --COLUMN--.

In the drawings, sheet 15 of 48, FIG. 14, video processor 1400, delete "VIEDEO" and insert instead--VIDEO--.

In Column 4, line 47, delete "12" and insert instead--1/2--.

In Column 5, line 13, delete "e.g." and insert instead--e.g.,--

line 35, delete "6,253,375" and insert instead --6,253,375,--.

In Column 6, line 62, delete "FIG. 1." and insert instead --FIG. 1--.

In Column 9, line 34, delete "1381-1" and insert instead --13818-1--.

In Column 13, lines 29-30, delete "p ackets" and insert instead --packets--.

In Column 15, line 31, delete "9/359,560," and insert instead --09/359,560,--.

In Column 16, line 46, delete "t15" and insert instead --t15--.

In Column 17, line 30, delete "t15" and insert instead --t15--;

line 52, delete "percent" and insert instead --per cent--.

In Column 19, line 25, delete "exacts" and insert instead --extracts--;

line 27, delete "display. i.e." and insert instead --display, i.e., --;

line 28, delete ". IPG" and insert instead --, IPG--.

MAILING ADDRESS OF SENDER: PATTERSON & SHERIDAN, LLP 595 Shrewsbury Avenue, Suite 100 Shrewsbury, New Jersey 07702

PATENT NO. _____7,058,965 B1_____ No. of additional copies

o. or additional copies

additional copies

ن در در در

Atty Docket No: SEDN/246

UNITED STATES PATENT AND TRADEMARK OFFICE **CERTIFICATE OF CORRECTION**

PATENT NO : 7,058,965 B1 Page 2 of 3

DATED

: June 6, 2006

INVENTOR(S) : Donald F. Gordon et al.

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

In Column 21, line 18, delete "B-picture" and insert instead --B-pictures--.

line 6, delete "reorganization" and insert instead --re-organization--; In column 22, line 53, delete "t 15" and insert --t15--;

In column 23, line 9, delete "1704. Is" and insert instead --1704, is--; line 26, delete "multiplexer," and insert instead --multiplexer;--.

In column 24, line 16, delete "date" and insert instead --data--.

In column 27, line 26, delete "POD" and insert instead --PID--;

line 40, delete "In" and insert instead --in--; line 44, delete "Is" and insert instead --is--; line 58, delete "In" and insert instead --in--.

In column 28, line 7, delete "equipment" and insert instead -equipment.--; line 29, delete "PID-I" and insert instead --PID-1--;

In column 34, line 18, delete "Is" and insert instead --is--; line 62, after "various" delete "a".

In column 35, line 64, delete "the" and insert instead -- The--.

line 40, after "(b)" insert --1/2--; In column 39, line 54, delete "1 hour" and insert instead -- 1/2 hour--.

MAILING ADDRESS OF SENDER PATTERSON & SHERIDAN, LLP 595 Shrewsbury Avenue, Suite 100 Shrewsbury, New Jersey 07702

PATENT NO.

7.058.965 B1 No. of additional copies





UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

PATENT NO : 7,058,965 B1

Page 3 of 3

DATED

: June 6, 2006

INVENTOR(S) : Donald F. Gordon et al.

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

In column 41, line 12, delete "Is" and insert instead --is--;

line 16, delete "If" and insert instead --if--; line 65, after "packetizer" delete "adapted".

In column 42, line 4, after "assigner" delete "adapted".

In column 43, line 1, delete "Performing" and insert instead --performing--.

line 7, delete "Particular" and insert instead --particular--.

In column 44, line 6, delete "5" and insert instead --5,--.

MAILING ADDRESS OF SENDER
PATTERSON & SHERIDAN, LLP
595 Shrewsbury Avenue, Suite 100
Shrewsbury, New Jersey 07702

PATENT NO.

_7,058,965 B1 ____ No. of additional copies

additional copies

Atty Docket No: SEDN/246

UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

PATENT NO : 7,058,965 B1

Page 1 of 3

DATED

: June 6, 2006

INVENTOR(S) : Donald F. Gordon et al.

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

In the first page, item (75), Inventors, line 5, delete "Shores" and insert instead -- City--.

In the drawings, sheet 12 of 48, FIG. 11, matrix entry 1130, below boxes containing "g1," "g2," "g3," and "g10" delete "COLUM" and insert instead --COLUMN--.

In the drawings, sheet 15 of 48, FIG. 14, video processor 1400, delete "VIEDEO" and insert instead--VIDEO--.

In Column 4, line 47, delete "12" and insert instead--1/2--.

In Column 5, line 13, delete "e.g." and insert instead--e.g.,--

line 35, delete "6,253,375" and insert instead --6,253,375,--.

In Column 6, line 62, delete "FIG. 1." and insert instead --FIG. 1--.

In Column 9, line 34, delete "1381-1" and insert instead --13818-1--.

In Column 13, lines 29-30, delete "p ackets" and insert instead --packets--.

In Column 15, line 31, delete "9/359,560," and insert instead --09/359,560,--.

In Column 16, line 46, delete "t15" and insert instead -t15-.

In Column 17, line 30, delete "t15" and insert instead --t15--;

line 52, delete "percent" and insert instead --per cent--.

In Column 19, line 25, delete "exacts" and insert instead --extracts--;

line 27, delete "display, i.e.," and insert instead --display, i.e.,--;

line 28, delete ". IPG" and insert instead --, IPG--.

MAILING ADDRESS OF SENDER: PATTERSON & SHERIDAN, LLP 595 Shrewsbury Avenue, Suite 100 Shrewsbury, New Jersey 07702 PATENT NO. __

___7,058,965 B1___ No. of additional copies



UNITED STATES PATENT AND TRADEMARK OFFICE **CERTIFICATE OF CORRECTION**

PATENT NO

: 7,058,965 B1

Page 2 of 3

DATED

: June 6, 2006

INVENTOR(S) : Donald F. Gordon et al.

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

In Column 21, line 18, delete "B-picture" and insert instead --B-pictures--.

line 6, delete "reorganization" and insert instead --re-organization--; In column 22, line 53, delete "t 15" and insert --t15--;

line 9, delete "1704. Is" and insert instead --1704, is--; In column 23, line 26, delete "multiplexer," and insert instead --multiplexer;--.

In column 24. line 16, delete "date" and insert instead --data--.

In column 27. line 26, delete "POD" and insert instead --PID--; line 40, delete "In" and insert instead --in--; line 44, delete "Is" and insert instead --is--;

line 58, delete "In" and insert instead --in--.

In column 28, line 7, delete "equipment" and insert instead -equipment.--: line 29, delete "PID-I" and insert instead --PID-1--:

In column 34, line 18, delete "Is" and insert instead --is--; line 62, after "various" delete "a".

In column 35. line 64, delete "the" and insert instead -- The--.

In column 39, line 40, after "(b)" insert --1/2--; line 54, delete "1 hour" and insert instead -- 1/2 hour -- .

MAILING ADDRESS OF SENDER PATTERSON & SHERIDAN, LLP 595 Shrewsbury Avenue, Suite 100 Shrewsbury, New Jersey 07702

PATENT NO. _

7,058,965 B1

No. of additional copies



Under the Paperwork Reduction Act of 1995, no persons are required to respond to a collection of information unless it displays a valid OMB control number.

UNITED STATES PATENT AND TRADEMARK OFFICE **CERTIFICATE OF CORRECTION**

PATENT NO : 7,058,965 B1 Page 3 of 3

DATED

: June 6, 2006

INVENTOR(S) : Donald F. Gordon et al.

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

In column 41, line 12, delete "Is" and insert instead --is--;

> line 16, delete "If" and insert instead --if--; line 65, after "packetizer" delete "adapted".

In column 42, line 4, after "assigner" delete "adapted".

In column 43, line 1, delete "Performing" and insert instead --performing--.

line 7, delete "Particular" and insert instead --particular --.

In column 44, line 6, delete "5" and insert instead --5,--.

MAILING ADDRESS OF SENDER PATTERSON & SHERIDAN, LLP 595 Shrewsbury Avenue, Suite 100

Shrewsbury, New Jersey 07702

PATENT NO. _

7,058,965 B1 No. of additional copies

additional copies



Atty Docket No: SEDN/246